

Caples Lake Gage
March 19, 2018








Sand Flat March 6, 2018

• Began intermittently transmitting on February 18, 2018.



Checked Datalogger and GOES Radio – No problem found

Forgot wattmeter, but had internet access to check NESDIS Field Test
 Power very low or non-existent

Looked at the antenna cabling and saw this...




Determined the cable was bad due to poor anchoring and would need to be replaced


No ladder available due to snow – Would repair at a later date

Sand Flat

May 30, 2018









Slate Creek

July 25, 2018
















Snow Mountain

July 26, 2018


















Red Rock Mountain

- August 14, 2018
- New Packer –Diamond G Outfitters















Bonanza King

• August 21, 2018





Middle Boulder 3

• August 22, 2018















Volcanic Knob

August 30,2018







• September 5, 2018

Central Sierra Snow Lab











Poison Ridge

October 23, 2018



Chilkoot Meadow

October 24, 2018






























































































CHECK IT OUT!

See rainfall accumulation, air temperature, and the amount of water in the snow pack (if available) and snow depth (if available)

http://cdec.water.ca.gov/cgi-progs/queryF?s= CHM

Courtesy of your United States Bureau of Reclamation and/or the California Department of Water Resources

(Note the absence of the www)

CALIFORNIA COOPERATIVE SNOW SURVEYS

AUTOMATIC SNOW SENSOR

CHM, Chilkoot Meadow

During the winter, instrumentation at this site measures the water content of the snow from which forecasts of your future water supply are made.

CDEC.WATER.CA.GOV

STATE OF CALIFORNIA
THE RESOURCES AGENCY OF CALIFORNIA
DEPARTMENT OF WATER RESOURCES







